

SPEC SHEET + MEASUREMENTS

PORt AUTHORITY.

Port Authority® Long Sleeve Carefree Poplin Shirt. W100

Product photo



Lightweight and breathable, our cotton-rich shirts keep their professional edge thanks to a stain-release finish, which releases stains during washing. Budget-friendly and durable, these virtually carefree shirts feature an Easy Care blend and finish. They also color-coordinate with our Core Classic Pique styles for seamless uniforming.

- 3.3-ounce, 55/45 cotton/poly
- Easy Care
- Stain release
- Breathable
- Dyed-to-match buttons
- Button-down collar
- Back box pleat
- Left chest pocket
- Rounded adjustable cuffs

CARE INSTRUCTIONS

Machine wash cold with like colors. Only non-chlorine bleach if needed. Tumble dry low. Warm iron, if needed.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

POR T AUTHORITY

Port Authority® Long Sleeve Carefree Poplin Shirt. W100

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Body Length at Back	30	31	32	33	34	35	35	36
Sleeve Length	33 3/4	34 1/2	35 1/4	36	36 3/4	37 1/2	38 1/4	39
Pocket Height	5 1/8	5 1/8	5 3/8	5 3/8	5 3/8	5 3/8	5 3/8	5 5/8
Pocket Width	4 5/8	4 5/8	4 7/8	4 7/8	4 7/8	4 7/8	4 7/8	5 1/8
Neck	17	17	17 1/2	18	19	19 3/4	20 1/2	21 1/4

Chest: Measured across the chest one inch below armhole when laid flat.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

Neck: Measured from center of button to center of buttonhole.

SPEC SHEET + MEASUREMENTS


PORT AUTHORITY.

Port Authority® Long Sleeve Carefree Poplin Shirt. W100

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	14 1/2-15	15-15 1/2	15 1/2-16	16-16 1/2	16 1/2-17	17-17 1/2	17 1/2-18	18-18 1/2
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® Long Sleeve Carefree Poplin Shirt. W100

COLORS

Please note: PMS code information is shown only when an exact match is available.



Burgundy
PMS 7428C



Carolina Blue
PMS 2142C



Deep Black
PMS BLACK
C



Deep Forest
Green
PMS 5605C



Graphite
PMS 7540C



Gusty Grey
PMS COOL
GRAY 8C



Rich Red
PMS 207C



River Blue
Navy
PMS 533C



True Royal
PMS 7687C



White